## Edit Time

Enter 600 for a 6:00 minute quarter

Enter 100 for a 1:00 minute intermission

**Edit Timeout**

Enter 2 for 2 timeouts



**Timeout Called**

Enter -1 Time Out



Hit Enter to start timeout

Push horn at 30 seconds and 15 seconds

After Timeout hits 0 seconds - hit CLEAR button to return back to clock